# **CAD-CUT® GLITTER**





# GLITTER FLAKE HEAT TRANSFER MATERIAL IS THE MOST POPULAR OPTION FOR CREA-TING SPECIAL EFFECTS.

Your design potential and possibilities are endless with over 38 colours to choose from!



# **AVAILABLE IN**

50 cm x 25 m rolls

# RECOMMENDED FABRICS

- 100% cotton
- 100% polyester\*
- Polyester-cotton mesh
- \* Test before application!

#### **CUTTING NOTES**

You should always test cut prior to any production run. Remember cutter settings will need to be adjusted as the blade ages. For optimal cutting and weeding, maintain a line thickness of at least 1.5 mm (1/16") for lettering and logos.

# APPLICATION INSTRUCTIONS

- Temperature: 150°C
- Time: 10 sec.
- Pressure: medium
- (#4-6 on Hotronix®)
- Peel: hot

# MULTI-COLOUR DESIGNS

CAD-CUD® Glitter is not recommended for multi-layer appication.

# ACCESSORIES RECOMMENDED

- Grip Cover Sheet
- Cover Sheet Non-Sticky
- EZ Weeder®

# CARE INSTRUCTIONS

Machine wash up to 40° C using mild detergent. Do not use bleach. Dry at normal dryer settings on household machines. Do not dry-clean. Can be directly ironed.

#### **STORAGE**

Store in cool, dry area. Avoid direct heat, sunlight and humidity.

# **DETAILS**









Ironable only

inside out















Peel hot







Sublimation



← Stretchable



Flock



